
# Reccomended Spare/Replacement Parts for Your Machine

| | |
|---|---|
| **Customer Name** | Flores Automation |
| **Job Number** | FC-20-17356 |
| **Part Name** | Rubber Check Valve |



**We have parts for all your vibratory feeder needs! If you have a system down, or would just like to keep some spares on the shelf we have you covered. We can next day air UPS or FedEx to your location domestic and international along with Saturday delivery if needed.**

Feeding Concepts Inc.
317.773.2040
Parts@feedingconcepts.com

*****Please send all purchase orders to parts@feedingconcepts.com. All credit card transactions must be through our Quote Valet System*****

| FCI Part Number | Description | MPN | Quantity on Machine Shipped | Estimated current value | Notes |
|---|---|---|---|---|---|
| E-0379 | Electromagnetic Coils for Base Drive | 379 | 2 | Request Quote | |
| SP-24 | Steel Springs for 24" Base Drive | SP24 | 13 | Request Quote | |
| E-0383 | Electromagnetic Coil for Inline Driver | 383 | 1 | Request Quote | |
| SP-IN | Springs for FCI Wide 2 Hanger Inline | SPIN | 6 | Request Quote | 2-1/2" X 3-1/2" X 3/32" (3) 2-1/2" X 3-1/2" X 1/8" (3) |
| NA | 12 Cubic Foot Belt Hopper | NA | 1 | Request Quote | Parts and Repair Kits Available upon Request |
| 148 | Brushless DC Motor for Belt Hopper | BLM5120HP-GFV | 1 | Request Quote | |
| 150 | Oriental Motor Driver | BLE2D120-A | 1 | Request Quote | |
| 10 | Keyence Laser Sensor for Bowl Level | LRZH500CP | 1 | Request Quote | |
| 136 | Rodix FC-205 Plus Controller for Bowl / Inline | 121-2005 | 2 | Request Quote | |
| 151 | Balluff 12-48V Power Supply | PS-XA-1W | 1 | Request Quote | |
| 152 | Weidmueller Relay, 24VDC | B69 Series | 1 | Request Quote | |
| 149 | Crouzet Relay, 24VDC | BM1R16MV1 | 1 | Request Quote | |

| | | | | |
|---|---|---|---|---|
| 154 | Omron 12 VDC Relay | G2R-1-S | 1 | Request Quote |
| 153 | Fuse Holders | USGCC1 | 1 | Request Quote |