Reccomended Spare/Replacement Parts for Your Machine

Customer Name	MVB Improvements
Job Number	FC-21-17596
Part Name	3/16" Ball Bearing

Feeding Concepts Inc.
317.773.2040
Parts@feedingconcepts.com

*****Please send all request for quotes and purchase orders to parts@feedingconcepts.com. All credit card transactions must be done through our Quote Valet system*****

FCI Part Number	Description	MPN	Quantity on Machine Shipped	Notes
E-0381	120V Base Drive Coils	381	2	
SP-8	Steel Springs for 8" T-West Base Drive Unit	SP8	4	(4) 3/16" Thickness
#24	Rubber Isolation Feet for Base Drive Unit	24	4	1" X 1" Rubber
109	Rodix FC-200 Controller for Bowl	1210002000	1	