Reccomended Spare/Replacement Parts for Your Machine

Customer Name	MVB Improvements
Job Number	FC-21-17597
Part Name	5-32" Ball Bearing

Feeding Concepts Inc.
317.773.2040
Parts@feedingconcepts.com

*****Please send all request for quotes and purchase orders to parts@feedingconcepts.com. All credit card transactions must be done through our Quote Valet system*****

FCI Part Number	Description	MPN	Quantity on Machine Shipped	Notes
V1C6	120V Base Drive Coils	381	2	
SP-8	Steel Springs for 8" J&J Base Drive Unit	SP8	5	(4) 1/4" (1) 3/16" Thickness
#24	Rubber Isolation Feet for Base Drive Unit	24	4	2" X 2" Rubber
109	Rodix FC-200 Controller for Bowl	1210002000	1	