INSTRUCTIONS FOR FC-22-18681

	Large Rectangle	Medium Square	Small Square
			
Air Jet #1	On	On	On
Air Jet #2	On	On	On
Air Jet #3	Off	Off	On
Bowl Confinement	.184”	.260” @ Discharge .280” Lead-in	.150”
Conveyor Confinement	.184”	.255”	.170”
Camera Program	P_000YellowD P_001BlackD	P_0002	P_0004
Air Pressure	70psi	70psi	70psi
Bowl Speed	20%	28%	20%
Conveyor Speed	700	650	700
Trigger Delay	12ms	7ms	7ms
Output One Shot	200ms	200ms	200ms
Output On Delay	35ms	35ms	35ms