Reccomended Spare/Replacement Parts for You[illegible]e

Customer Name	MVB Improvements
Job Number	FC-22-18985
Part Name	Lens

Feeding Concepts Inc.
317.773.2040
Parts@feedingconcepts.com

Please send all request for quotes and purchase orders to parts@feedingconcepts.com. All credit card transactions must be done through our Quote Valet system

FCI Part Number	Description	Quantity on Machine Shipped	Notes
Bowl/Hopper/Inline Parts			
E-0379	E Series Vibratory Coil for Drive Unit	2	
SP-18	Steel Springs for 18" T-West Base Drive Unit	12	(11) 3/8" (1) 1/4"
#24	Rubber Isolation Feet for Base Drive	4	
E-0185	E Series Vibratory Coil for Hopper Driver	1	
SP-HP	Springs for Hopper Driver	3	(3) 1/8"
#27	Rubber Isolation Feet for Hopper Driver	4	
E-0383	E Series Vibratory Coil for Inline Driver	1	
SP-IN	Springs for Inline Driver	4	(3) 1/8" (1) 3/32"
Control Components and Sensors			
109	Rodix Controller for Bowl / Hopper / Inline	3	
FU-77TZ	Keyence Fiber Unit	1	
FS-N41C	Keyence Main Unit Amplifier	1	

Q4XTBLAF500-Q8	Banner Q4X Laser Sensor for Bowl Level Control	1
250	Lumberg Cordset for Q4X Sensor	1
Other		
Aw30-N02E-Z-D	SMC Air Filter / Regulator	1
PCM10-125-02B	2 Port Air Outlet Manifold	1
FCI100	Flexible, Mountable Airjet Assembly	1