Reccomended Spare/Replacement Parts for Your Machine

Customer Name	Solvis
Job Number	FC-23-19409
Part Name	Blister Pack

Feeding Concepts Inc.
317.773.2040
Parts@feedingconcepts.com

Please send all request for quotes and purchase orders to parts@feedingconcepts.com. All credit card transactions must be done through our Quote Valet system

FCI Part Number	Description	Quantity on Machine Shipped	Notes
Bowl and Drive			
E-0379	E Series Vibratory Coil for Drive Unit	4	
SP-30-316	3/16" Steel Springs for 30" Drive Unit	18	
#24	Rubber Isolation Feet for Base Drive	4	
WB Hopper Parts	**SN: 412897**		
P2-14-036	Replacement Belt for Hopper Conveyor, 14 X 36, P2 Style	1	
30-7114	14" Universal Idler Pulley Assembly	1	
40-7314-R-SM5M	14" LP Drive Pulley Assembly	1	
BLM460SHP-GFV	Oriental Motor Brushless DC Motor	1	
GFV-4G100AS	100:1 Gearhead for Motor	1	
CC030KHBLF	Oriental Motor 3M Cable for Motor to Driver	1	
Outfeed Conveyor	**SN: 412898**		
U1-04-036	Replacement Belt for Outfeed Conveyor	1	
30-7304	4" Universal Idler Pulley Assembly	1	

40-4001-R-SM5M	4" LP Drive Pulley Assembly	1
BLM460SHP-GFV	Oriental Motor Brushless DC Motor	1
GFV-4G15AS	100:1 Gearhead for Motor	1
CC040KHBLF	Oriental Motor 3M Cable for Motor to Driver	1
Control Components		
BAE0111	Balluff 12-48V Power Supply	1
121-000-2005	Rodix FC-205 Plus Controller for Bowl	1
BLE2D60-A	Oriental Motor, Driver for WB Hopper and Outfeed	2
Sensors and Cables		
Q4XTBLAF500Q8	Banner Q4X Laser Sensor for Bowl Level	1
Q4XTBLAF300Q8	Banner Q4X Laser Sensor for Track Switch	1
RKT4-225/5M	Lumberg Cordset for Q4X	2
Other		
M150-34-6	Extra Large Machine Leveling Feet	4